Sample Home Inspection Report

Cowtown Home & Property Inspections — placeholder for client report

1. Roof covering

Priority: Repair — Damaged shingles photographed at south slope.

2. Electrical panel

Priority: Safety — Further review by a qualified electrician recommended.

3. Furnace

Maintenance — Replace filter and service before next heating season.